

**THIS FORM MUST BE COMPLETED AND SIGNED BY AN MVD  
AGENT, LAW ENFORCEMENT OFFICER OR  
MILITARY/CAMPUS POLICE AS PROOF OF VEHICLE  
UNAVAILABILITY**

**STATE OF NEW MEXICO - MOTOR VEHICLE DIVISION  
AFFIDAVIT OF V.I.N. INSPECTION**

In or Out-of-State Inspection


Vehicle inspections must be conducted by an authorized New Mexico (or other state) MVD Agent, employee or full time law enforcement officer.

Name of Registered Owner  
at Time of Inspection

**VEHICLE INFORMATION (Complete where applicable)**

YEAR 2010	MAKE Chrysler	MODEL Pacifica	TYPE Van	STATE REGISTERED CO
Vehicle Identification Number 1G1YD2.0W3A5171345				
Vehicle Odometer Reading 26,504 mi		Vehicle License Plate No. —		
Vehicle Location Colorado	State Colorado	County El Paso	City Colorado Springs	

I CERTIFY THAT THE IDENTIFICATION NUMBER RECORDED HEREIN IS ON THE VEHICLE DESCRIBED ABOVE CLAIMED TO BE OWNED BY THE PERSON OR BUSINESS INDICATED, THAT I HAVE CONDUCTED A VISUAL INSPECTION ONLY AND THAT I AM NOT INVOLVED IN OR RESPONSIBLE FOR ANY OTHER ACTIVITIES OR TRANSACTIONS RELATED TO THIS VEHICLE.

Inspector's Printed Name Bachman, Luvica		
Inspector's Signature 	Badge or ID No. 4582	Date 11-28-2014
Agency / Dealer Name Colorado Springs Police Department		State CO

Please return this affidavit with supporting documentation to the  
City of Albuquerque [Fax (505) 764-1101] or mail to:

City of Albuquerque Vehicle Pollution Management Program  
1500 Broadway NE  
Albuquerque, New Mexico 87102

\*\*\*IF YOU HAVE ANY QUESTIONS CONTACT OUR OFFICE AT (505) 764-1110\*\*\*